
## **Keyless High Torque Timing Pulleys - P8M**

Compatible with P8M Type from Tsubakimoto Chain Co.

## For High Torque Timing Belts, see F.1467.



Alterations   Part Number   - Pulley Shape   - Shaft Bore Dia.   FC, NFC, UFC, RFC, BMC, BMR, OP   PTL/30F98M250 - F - 20 - BMC									
Alterations	Flange Cut	Flange Not Swaged	Flange Swaged on One Side	Surface Treatment	Pulley for Replacement (Pulley only)				
Code	FC	NFC	LFC, RFC	BMC, BMR	OP				
	Lowers flange by cutting. FC: 0.5mm Increment	installed.	bushing side (LFC) or the opposite	Applies electroless nickel plating on a bushing.  (Antirusting treatment is applied to screws.)					

Aiterations	i lalige out	i lalige ivol Swageu	I lalige Swageu oil Olle Side	Surface freatment	rulley for neplacement (rulley only)
Code	FC	NFC	LFC, RFC	BMC, BMR	OP
Spec.	Lowers flange by cutting. FC: 0.5mm Increment  No surface treatment is applied on flange circumference.  FC≥(0,0)+1 FC≥6-2  Indexing Code FC35	Flange is not installed. (Flange Included)	Flange is installed on either the bushing side (LFC) or the opposite side (RFC) prior to shipping, (Flange 1 pc. Included)  (LFC) (RFC) (RFC)	Applies electroless nickel plating on a bushing. (Antirusting treatment is applied to screws.)  ♥ Electroless nickel plated bushing decreases allowable torque by 20 ~ 30%.  BMC:Not RoHS Compliant (Screw: SCM435 Dacrotized Treatment)  BMR: RoHS Compliant (Screw: SCM435 GeoMet Coating)  ♥Not applicable to PTLM and PTLG.	Pulleys will be shipped bushings uninstalled.