Key Features

■Automatic tool change in multiple grippers and tools

Vast reduction in changeover time as well as automation for numerous types of application and workpieces

■Anti-drop mechanism for standard models

Grippers and other tools can be retained even at a sudden air loss, and which prevents peripheral devices from being damaged

■Various options

Various options such as electrode (15-pin for electric signals, signal cable, and D-sub connector), tool stands (for 1 or 2-piece), and check valves.



How To Order

■Robot Side

Standard ----- KHC-1R

Option ----- KHC - 5 R - D1 ---- D1 Electrode mounted on KHC-5 Robot Side

Size		Parts		
Symbol		Symbol	Name	
1		R	Robot Side Only	
5				
10			I I	
20				

Size Parts Option

Option					
Symbol	Name				
D1	Electrode (15-pin)				
D ₂	Electrode + Signal Cable (1m)				
D 3 *	Electrode + D-Sub Connector (Socket)				
В *	Check Valve				
Z	Special Type (Custom)				
Freezet KUO 1D					

*Except KHC-1R

For option detail >36P



■Tool Side

Standard ----- KHC-1H

Option CHC - 5 H - D ---- KHC-5H & its Electrode

Size			Parts		
Symbol		Symbol	Name		
1		Н	Tool Side Only		
5			1		
10					
20					

*Except KHC-1H

For option detail > 36P